
NPEXA-C7 3
Isolated Safety Barrier

Rotary switch	Distribution
S0	5 V DC, 00 mA
S	6 V DC, 00 mA
S2	8 V DC, 50 mA
S4	9 V DC, 50 mA
S8	2 V DC, 50 mA

B. Pry the metal lock off the rail with screwdriver as arrow
arrow